

ENVIRONMENTAL PROFILES, INCORPORATED

Project: (formerly) **Magnussen Buick** **Location:** **550 El Camino Real, Menlo Park, California**
Revised by: **mcb** **Approved by:** **mjlw** **Job No.** **102099** **21 May 2003**

EXPLANATION

- | | | | | | |
|---|------------------------------------|-----|--------------------------------|---|---|
| ● | Groundwater monitor well location | 6K | Former UST location & capacity | ♂ | Dual piston, below grade lift (removed 11-2000) |
| ⬮ | Soil boring location | WSH | Former fuel dispenser location | ○ | Single piston, below grade lift (removed 11-2000) |
| ● | Soil sample location (approximate) | AGT | Oil Water Separator (OWS) | H | Above ground electric lift |
| | | | Above ground storage tank | ■ | Floor drain |
- Map Source: Monitor Well & Site Survey, updated by Meridian Engineering, Inc., (4/03)

FIGURE 2 - SITE DIAGRAM

